

19 DEC 69 16 35 225×1

S E C R E T 191625Z DEC 69 7654 PRIORITY

EVALUATION OF C289C

SUBJECT: IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MISSION IS GOOD AND COMPARABLE TO THAT OBTAINED FROM MISSION C259C. THE MAJOR CONTRIBUTING FACTOR OF THIS GOOD QUALITY RATING IS THE PREDOMINANCE OF CLOUD FREE PHOTOGRAPHY THROUGHOUT THE MISSION. CLOUD COVER OBSCURES APPROXIMATELY 10 PERCENT OF THE ENTIRE MISSION. THE INTERPRETATION SUITABILITY IS RATED AS FAIR TO GOOD.

- 2. MISSION DATA:
 - Α. C289C
 - В• 26 NOV 69
 - C. H/002/U2R
 - MODE 5, 40 70 DEG. LEFT D.
 - T/0: Ø2ØØZ, C/ON: Ø332Z E.
 - 3400
 - 80 IN/SEC G.
 - W-12 Н.
 - I.
 - ORIGINAL NEGATIVE:
- EXPOSURE: ADEQUATE FOR INTERPRETATION PURPOSES.
 - В. DENSITY AND CONTRAST: GENERALLY MEDIUM.
- IMAGED DEGRADATIONS: TWO MINUS DENSITY LINES, LOCATED 2.3 AND 2.5 INCHES FROM THE TAKE-UP END OF THE FORMAT AND PARALLEL TO THE MINOR AXIS, EXTEND ACROSS THE FORMAT ON ALL FRAMES OF THE MISSION. FOG PATTERNS ARE PRESENT ON FRAMES 2 AND 3. THESE APPEAR TO E ASSOICATED WITH CAMERA START-UP.
- D. PHYSICAL DEGRADATIONS: THREE HEAT SPLICES AND ONE MANUFACTURER'S SPLICE ARE PRESENT ON THIS MISSION.
- E. THE IMAGE OF THE CAMERA SERIAL NUMBER AND SLIT METER IS OUT OF FOCUS AND DIFFICULT TO READ.
 - F. OTHER: THE LAST TITLED FRAME IS 4357.
- POSITIVES: SUITABLE FOR INTERPRETATION PURPOSES. SECRET

		STRIBUTION		
-	COX	OFFICE	PI	
1-	COL	FILE		
1	4	WILLE SEC.		
1		1, 15.1/2D		
1		a Energy		
4	P 61		1) (
\$	3,4	11/11/2	1	
1		Pan d	1	25X1
Ħ		T.Est		
4		7.3.30	1	
1		4000	-	
4	T of the second second	THE	-	
1		TELL OD	1-	
B		PASTEEN.	-	t
7		WEER	-	t
200		FAS:	-	ĺ
BE		MAS	+	t .
		ZEC/PED	┦	ł
		120		ŧ .
	13	DYA-XX4		ł
VE	-00	I I YSPAD	+	•
•		TOYA-AP		•
		101A-HI	-	1 25V
		(7577)		1 25 X ′
	-	CATX	+	1
		 		4
				1
		1 To 100 1	-	

ADVANCE CY SANITIZED WITH TEXT

-- END OF MESSAGE --

